

## DAF - XF 480 DAMAGED VEHICLE GOOD ENGINE

### Specificaties

| Algemeen            |            |
|---------------------|------------|
| Brand               | DAF        |
| 1e afgifte kenteken | 2018-02-22 |
| Motorvermogen       | 355 KW     |
| Euronorm            | Euro6      |
| Referentie nummer   | 20754      |
| Chassis             |            |
| As configuratie     | 2389       |
| Eigen gewicht       | 7717 KG    |
| Laadvermogen        | 11783 KG   |
| Totaal gewicht      | 19500 KG   |
| Wielbasis           | 380        |
| Opties              |            |
|                     |            |
| Afmetingen          |            |
| Lengte              | 592 CM     |
| Breedte             | 255 CM     |

REFERENCE NUMBER: 20754

DAF XF 480 Spacecab Damaged vehicle with ABS,Airco,Aluminium tank,Webasto,Fridge,Euro 6,Ad-blue,Digitale tacho,Radio,DEB,Spoilers,Suspension Steel/Air,AS-Tronic gearbox.  
Truck with damaged cabine with 219.000km, in our yard. is with driver's seat.  
Good working engine!



### Assen

| 1) 50% 50%         |                        |
|--------------------|------------------------|
| Vering             | Leaf spring suspension |
| Banden maat        | 385/65 R 22.5          |
| Stuuras            | Ja                     |
| 2) 25% 25% 25% 25% |                        |
| Reductie           | Single reduction       |
| Vering             | Air suspension         |
| Banden maat        | 315/70 R 22.5          |
| Stuuras            | Nee                    |